



OPTIONAL:
Tool-side change-adapter MT_BGR00020310

m= kg	A	p= bar
proj. storage surface = m²		v= l/min
First angle projection	P= kW	
	U= V / Hz / Ph	
	Imax= A	

12

11

10

9

8

7

6

5

4

3

2

1

H

G

F

E

D

C

B

A

12

11

10

9

8

7

6

5

4

3

2

1

○ All fastening holes $\varnothing 17,5$ mm for screws M16 (DIN ISO 4014/4017 -8.8) without washers. Fastening holes are coloured red.

● Fastening holes filled blue are difficult to access. We recommend using fastening holes coloured red.

● Drilling holes for locating pins are filled red. Recommend dimensions of locating pins: $\varnothing 12$ h6

Z (2:1)

