


m= kg	A	p= bar
proj. storage surface = m ²	P= kW	v= l/min
U= V / Hz / Ph	I _{max} = A	

12 11 10 9 8 7 6 5 4 3 2 1

○ All fastening holes Ø17,5 mm for screws M16 (DIN ISO 4014/4017 -8.8) without washers. Fastening holes are coloured red.

● Fastening holes filled blue are difficult to access. We recommend using fastening holes coloured red.

● Drilling holes for locating pins are filled red.



12 11 10 9 8 7 6 5 4 3 2 1