


Tool Center Point  
TCP (on the plane of the flange)

TCP - working range


Depending on  
the drive type



Interference contour  
from machine body

Maximum interference  
contour

Z (1:1)



Connecting dimensions,  
valid for article number A\_00805-01

m= kg	A	p= bar
proj. storage surface = m²		v̇= l/min
First angle projection	P= kW	U= V / Hz / Ph
	U=	I <sub>max</sub> = A



A\_00805-01

12

11

10

9

8

7

6

5

4

3

2

1

H

G

F

E

D

C

B

A

A

B

C

D

E

F

G

H


H

12

○ All fastening holes  $\varnothing 17,5$  mm for screws M16 (DIN ISO 4014/4017 -8.8) without washers. Fastening holes are coloured red.

● Fastening holes filled blue are difficult to access. We recommend using fastening holes coloured red.

● Drilling holes for locating pins are filled red. Recommend dimensions of locating pins:  $\varnothing 12$  h6.



12

11

10

9

8

7

6

5

4

3

2

1

A

B

C

D

E

F

G

H